




HP XAFS Setup at HXMA



1. Supporting, screwed to table;
2. Huber stage, vertical;
3. Huber stage, horizontal;
4. Huber stage, rotation;
5. Kohzu stage, pitch;
6. Adapter to cells;
7. Alignment accessory with square & circle opening, coaxial to "4", "5", "6" & cell center. The "line" alignment accessories are coming.

New feature

1. Original ADC stages "2" & "3" replaced by Huber stages;
2. Additional Huber rotation stage "4";
3. Alignment accessory.

